## INSTRUCTION SHEET



KEPCO An ISO 9001 Company.


MA RCW/AE -800H


## **MOUNTING ADAPTER RCW/AE-800H**


**DESCRIPTION.** The Model MA RCW/AE-800H Mounting Adapter includes an adapter plate and mounting screws that allow a horizontally-mounted 800W AE power supply to be easily substituted for a horizontally-mounted 350W RCW power supply. Note that some AE dimensions may exceed corresponding RCW dimensions; verify proper fit prior to installation. Mount the adapter plate to the AE power supply using the screws and spacers provided (see Figure 1), then install the adapter plate in place of the RCW power supply using the screws previously used to mount the RCW power supply.

## NOTES:

- MOUNT ADAPTER PLATE TO POWER SUPPLY AT HOLES "A" USING THREE SPACERS P/N 104-0312, AND THREE SCREWS P/N 101-0487.
- 2. REMOVE RCW POWER SUPPLY AND SAVE MOUNTING SCREWS, THEN INSTALL ADAPTER PLATE WITH AE POWER SUPPLY ATTACHED AT HOLES "B." USING MOUNTING SCREWS SAVED. MOUNTING SCREWS ARE M4, LENGTH NOT TO EXCEED 8 MM.







3044736

## FIGURE 1. ADAPTER PLATE INSTALLATION

KEPCO, INC. ● 131-38 SANFORD AVENUE ● FLUSHING, NY. 11355 U.S.A. ● TEL (718) 461-7000 ● FAX (718) 767-1102 www.kepcopower.com ● email: hq@kepcopower.com