


# INSTRUCTION SHEET




**KEPCO** An ISO 9001 Company.

**MA  
RAX/RTW  
300H**

## MOUNTING ADAPTER RAX/RTW 300H

**DESCRIPTION.** The RoHS-compliant Model MA RAX/RTW 300H Mounting Adapter includes an adapter plate and mounting screws that allow a 300W RTW power supply to be easily substituted for a horizontally-mounted 300W RAX power supply. Mount the adapter plate to the RTW power supply using the screws provided (see Figure 1), then install the adapter plate in place of the RAX power supply using the screws that previously secured the RAX power supply.



### NOTES:

1. MOUNT ADAPTER PLATE TO RTW USING THREE SCREWS AND THREE SPACERS AT "A" HOLES AS SHOWN.
2. INSTALL ADAPTER PLATE WITH RTW ATTACHED USING "B" HOLES AND FOUR SCREWS PREVIOUSLY USED TO MOUNT RAX POWER SUPPLY (NOT SUPPLIED).
3. MAX. PENETRATION AT "B" (SCREW 8-32) MUST NOT EXCEED 5MM.

3043288

**FIGURE 1. ADAPTER PLATE INSTALLATION**

KEPCO, INC. ● 131-38 SANFORD AVENUE ● FLUSHING, NY. 11355 U.S.A. ● TEL (718) 461-7000 ● FAX (718) 767-1102  
<http://www.kepcopower.com> ● email: [hq@kepcopower.com](mailto:hq@kepcopower.com)